

INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME

HISTORIC

AND/OR COMMON

Hollingsworth Farm

2 LOCATION

STREET & NUMBER

NW corner, U.S. 301 and Md. 302

CITY, TOWN

Church Hill

☒ VICINITY OF

CONGRESSIONAL DISTRICT

1st

STATE

Maryland

COUNTY

Queen Anne's

3 CLASSIFICATION

CATEGORY

☐ DISTRICT☒ BUILDING(S)☐ STRUCTURE☐ SITE☐ OBJECT

OWNERSHIP

☐ PUBLIC☒ PRIVATE☐ BOTH

PUBLIC ACQUISITION

☐ IN PROCESS☐ BEING CONSIDERED

STATUS

☒ OCCUPIED☐ UNOCCUPIED☐ WORK IN PROGRESS

ACCESSIBLE

☒ YES: RESTRICTED☐ YES: UNRESTRICTED☐ NO

PRESENT USE

☒ AGRICULTURE☐ COMMERCIAL☐ EDUCATIONAL☐ ENTERTAINMENT☐ GOVERNMENT☐ INDUSTRIAL☐ MILITARY☐ MUSEUM☐ PARK☒ PRIVATE RESIDENCE☐ RELIGIOUS☐ SCIENTIFIC☐ TRANSPORTATION☐ OTHER:**4 OWNER OF PROPERTY**

NAME

Hollingsworth Farm Ltd. Partnership

Telephone #:

STREET & NUMBER

Box 101

CITY, TOWN

Church Hill

☐ VICINITY OF

STATE, zip code

Maryland 21623

5 LOCATION OF LEGAL DESCRIPTION

Liber #: MWM 174

COURTHOUSE,

REGISTRY OF DEEDS, ETC. Queen Anne's County Courthouse

Folio #: 643

STREET & NUMBER

Courthouse Square

CITY, TOWN

Centreville

STATE

Maryland

6 REPRESENTATION IN EXISTING SURVEYS

TITLE

DATE

☐ FEDERAL ☐ STATE ☐ COUNTY ☐ LOCALDEPOSITORY FOR
SURVEY RECORDS

CITY, TOWN

STATE

7 DESCRIPTION

QA-280

CONDITION

☐ EXCELLENT
☒ GOOD
☐ FAIR

☐ DETERIORATED
☐ RUINS
☐ UNEXPOSED

CHECK ONE

☐ UNALTERED
☒ ALTERED

CHECK ONE

☒ ORIGINAL SITE
☐ MOVED DATE _____

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

The Hollingsworth Farm is located on the northwest corner of Barclay Road and U.S. Route 301, approximately three miles east of Church Hill.

The house and farm buildings are located on a slight rise on the north side of Barclay Road, surrounded by open farm land.

The house is of frame construction, two stories high, five bays wide, and one room deep, with flush brick chimneys at either end of a large hipped roof. A two story frame wing with asymmetrical fenestration and a pitched gable roof projects from the east end of the rear facade, forming an L-plan house.

The front facade faces south, toward Barclay Road. There is a double door framed with sidelights and transom in the center bay of the first floor, flanked by two 6/6 windows on the first floor and five 6/6 windows on the second floor. The house rests on a low, continuous brick foundation and is covered with plain horizontal weatherboard siding and a stamped tin roof. Plain pilasters

CONTINUE ON SEPARATE SHEET IF NECESSARY

CONTINUATION SHEET

7.1 DESCRIPTION

with molded caps accentuate the corners; the eaves are boxed in with a deep soffit, complex crown mold, beveled bed mold and broad plain frieze board. Plain pilasters with Greek ogee caps frame the sidelights flanking the front door, and a band of rabbeted, geometric trim forms a Greek Revival lintel across the door opening. A similar band forms the smaller lintel between the door and the transom. The windows are set in plain frames with a simple drip mold across the opening and are fitted with louvered wood shutters. A small porch with simple columns stretches across the center three bays of the first story.

On the west gable, there are two 6/6 windows on the first and second story. The flush brick chimney is centered on the gable and the upper shaft has evidently been rebuilt. There are pilasters on both the front and rear corner; the cornice, siding, and roof all match the front facade in detail.

The two story rear wing covers the east two bays of the rear facade and a one story lean-to on the wing conceals the middle bay on the first story. There are two 6/6 windows to the west of the lean-to on the first floor and three 6/6 windows on the second floor. The window in the center bay of the second story is downset

CONTINUATION SHEET

7.2 DESCRIPTION

to accommodate the interior stair. The corner pilasters are omitted on this facade; the siding, cornice, roof and window trim matches the front facade.

On the east gable, there is one 6/6 window on each floor to the right of the chimney. The east wall of the rear wing is flush with this gable wall, and the siding runs continuous, uninterrupted by a seam or a pilaster. The gable wall matches the front facade in siding, cornice, roof, and window trim. The upper portion of the chimney has apparently been rebuilt.

The fenestration of the rear wing is asymmetrical. On the east wall, there are doors in the left and right bays on the first floor with two large 2/2 windows in the center on the first floor. On the second floor, there are two windows in the center. The left window has 2/2 sash, the right has 6/6 sash. The window frames are plain except for a Victorian drip cap. The siding runs continuous from the main house. The shallow pitched gable roof has boxed eaves with a plain piece of applied trim in place of a crownmold.

On the north gable wall of the wing, there is one 2/2 window to left of center on the first floor. The siding and rakeboards are plain.

A one story lean-to stretches across the west side of the rear wing. The south portion of this lean-to

CONTINUATION SHEET

7.3 DESCRIPTION

is enclosed with two small window openings, while the north portion consists of an open porch. A door in the north bay of the wing opens onto the porch on the first story. On the second story there is a 2/2 window in the center bay and a 6/6 window in the north bay. The cornice and siding match the east facade.

The interior was not accessible at this time.

PERIOD	AREAS OF SIGNIFICANCE -- CHECK AND JUSTIFY BELOW			
<input type="checkbox"/> PREHISTORIC	<input type="checkbox"/> ARCHEOLOGY-PREHISTORIC	<input type="checkbox"/> COMMUNITY PLANNING	<input type="checkbox"/> LANDSCAPE ARCHITECTURE	<input type="checkbox"/> RELIGION
<input type="checkbox"/> 400-1499	<input type="checkbox"/> ARCHEOLOGY-HISTORIC	<input type="checkbox"/> CONSERVATION	<input type="checkbox"/> LAW	<input type="checkbox"/> SCIENCE
<input type="checkbox"/> 1500-1599	<input type="checkbox"/> AGRICULTURE	<input type="checkbox"/> ECONOMICS	<input type="checkbox"/> LITERATURE	<input type="checkbox"/> SCULPTURE
<input type="checkbox"/> 1600-1699	<input checked="" type="checkbox"/> ARCHITECTURE	<input type="checkbox"/> EDUCATION	<input type="checkbox"/> MILITARY	<input type="checkbox"/> SOCIAL/HUMANITARIAN
<input type="checkbox"/> 1700-1799	<input type="checkbox"/> ART	<input type="checkbox"/> ENGINEERING	<input type="checkbox"/> MUSIC	<input type="checkbox"/> THEATER
<input checked="" type="checkbox"/> 1800-1899	<input type="checkbox"/> COMMERCE	<input type="checkbox"/> EXPLORATION/SETTLEMENT	<input type="checkbox"/> PHILOSOPHY	<input type="checkbox"/> TRANSPORTATION
<input checked="" type="checkbox"/> 1900-	<input type="checkbox"/> COMMUNICATIONS	<input type="checkbox"/> INDUSTRY	<input type="checkbox"/> POLITICS/GOVERNMENT	<input type="checkbox"/> OTHER (SPECIFY)
		<input type="checkbox"/> INVENTION		

SPECIFIC DATES

BUILDER/ARCHITECT

STATEMENT OF SIGNIFICANCE

The large frame house on the Hollingsworth Farm is an excellent example of a mid-19th century L-plan dwelling with virtually all of the exterior Greek Revival trim intact and in excellent condition. Significant details include the pilastered corners, the handsome Greek door surround and the cornice. Although hip roofs were widely used in the mid-19th century, local tradition suggests this one may have been altered from an original pitched gable roof. The interior was not accessible.

CONTINUE ON SEPARATE SHEET IF NECESSARY

9 MAJOR BIBLIOGRAPHICAL REFERENCES

QA-280

CONTINUE ON SEPARATE SHEET IF NECESSARY

10 GEOGRAPHICAL DATA

ACREAGE OF NOMINATED PROPERTY _____

VERBAL BOUNDARY DESCRIPTION

LIST ALL STATES AND COUNTIES FOR PROPERTIES OVERLAPPING STATE OR COUNTY BOUNDARIES

STATE

COUNTY

STATE

COUNTY

11 FORM PREPARED BY

NAME / TITLE

Orlando Ridout V, Historic Sites Surveyor

ORGANIZATION

Queen Anne's County Historical Society

DATE

3/17/82

STREET & NUMBER

TELEPHONE

CITY OR TOWN

Centreville

STATE


Maryland

Field Notebook QA-24; Recorded May 8, 1981.

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust
The Shaw House, 21 State Circle
Annapolis, Maryland 21401
(301) 267-1438





QA-280

Vickers Hollingsworth Farm
Rt. 302 and U.S. 301
Orlando Ridout V 1981
View from Southeast



QA-280

Vickers Hollingsworth Farm
Rt. 302 and U.S. 301
Orlando Ridout V 1981
View from Northwest